

Photomontage of the route of the underground cable



Figure 1: View of route of underground cable. Entrenched on the right edge of the road. Note existing overhead line on left. To be removed.



Figure 2: View of the route of underground cable where it deviates to the right to aim for the building.



Figure 3: View of route of underground cable towards the righthand corner of the building.